repartable 2021 MULTIBRANDS ELECTRONIC REPAIR



CD RADIO



NAVIGATION



CLUSTER



ENGINE CONTROL UNIT



BODY CONTROL UNIT



SUNROOF CONTROL UNIT



AIRCO PANEL



POWER STEERING CONTROL UNIT



STEERING WHEEL REMOTE CONTROL





Why choose Clarion?

FIXED PRICE FOR ANY FAILURE

Up to 80% saving compared with new part

FREE SHIPPING FORWARD AND RETURN

12 MONTHS WARRANTY

on all repairs

CONTROLLED DELAYS

Instrument clusters: 2 days* Other products: 2 to 5 days*

* average delays

shipping forward and return included

EASY AND QUICK

Pick-up and delivery at your place Repair request on www.reparlab.com

REPAIRER APPROVED BY CARMAKERS

Quality of a Tier-1 Origin Equipment Manufacturer

Who we are?

CLARION

Founded in 1947 Design and production of automotive radio & navigation systems











REPAIR PROCESS



step 01

Online repair request made by the dealer





step 02

Pick up of the defective unit on the same day by UPS for requests submitted before 12 AM



Arrival of the unit in our repair shops in the North-East of France



Repair, calibration, control



Return of the repaired unit to the dealer



Installation of the product in the car, 12 months warranty!

CONTENTS

Alfa Damas	04	Ford	E4	Nissan	70	KANGOO	104
Alfa Romeo	04	Ford	51	Nissan 350Z	72		
GIULIETTA		C-MAX		350Z 370Z		KOLEOS	
MITO	05	FIESTA	52	ALMERA		LAGUNA	
Audi	06	FOCUS	53			LATITUDE	
A1		FUSION	54			MASCOTT	
				e-NV200		MASTER	
A3		GALAXY		GTR		MEGANE	
A4		KA	54	JUKE		MODUS	
A6		KUGA	55	LEAF		SAFRANE	
<u>Q7</u>		MONDEO	56	MICRA		SCENIC	
Π	09	RANGER		MURANO		TRAFIC	
0''	40			NAVARA		TWINGO	147
Citroën	10	S-MAX	57	NOTE		VELSATIS	148
BERLINGO		TRANSIT	58	PATHFINDER		WIND	149
C1		Car diagnostic tool	58	PATROL		Z0É	149
C2				PRIMERA			
C3		Honda	59	PULSAR		Seat	150
C3 AIRCROSS	16			QASHQAI		ALHAMBRA	
C3 PICASSO	17			X-TRAIL	86	ALTEA	
C4	18	CR-V	59	Opel	87	ATECA	151
C4 AIRCROSS	20	CR-Z	60			EXE0	151
C4 CACTUS	21	INSIGHT	61	ADAM Antara		IBIZA	152
C4 PICASSO	21	JAZZ				LEON	152
C5				7.0.1.2.		TOLEDO	153
C6		LEGEND	60	CASCADA			
C8				CORSA		Škoda	154
C-CROSSER		Hyundai	62	INSIGNIA		FABIA	154
C-ELYSEE		I20	62	MERIVA		KODIAQ	154
		130	62	MOKKA		OCTAVIA	155
C-ZERO				ZAFIRA	93	RAPID	156
JUMPER		140		Peugeot	94	ROOMSTER	157
JUMPY		IX20	62	106		SUPERB	
NEMO		IX35	63	107		YETI	
XSARA		SANTA FE	63	1007			
XSARA PICASSO	34	TUCSON II		206		Subaru	160
	0.5	TUGOUN II	03	207		BRZ	160
Dacia	35	10	0.4	208		FORESTER	160
DOKKER		Infiniti	64	2008		IMPREZA	161
DUSTER		Q50	64	306		LEGACY	161
LODGY	36			307		LEVORG	161
LOGAN		Jeep	65	308			
SANDERO	36	RENEGADE	65	3008		Suzuki	162
				406		ALTO	162
DS	37	Kia	66	407		G.VITARA	162
DS3		CEE'D		4007		JIMNY	163
DS4						SWIFT	163
DS5		OPTIMA	66	4008		SX4	163
DS7	41	PICANTO	66	508 5008			
e	40	RIO	67			Volkswagen	164
Fiat	42	SORENTO	67	607		AMAROK	
500				807		CADDY	164
500L-500X		SPORTAGE		BIPPER		EOS	165
D0BL0	43	VENGA	67	BOXER		GOLF	166
DUCATO	44			EXPERT		JETTA	167
FIORINO	45	Lancia	68	ION		NEW BEETLE COCCINELLE	168
IDEA	46	MUSA	68	PARTNER		PASSAT	170
MULTIPLA	46	PHEDRA		RCZ		POLO	
PALIO				RIFTER	126	SCIROCCO	
PANDA		YPSILON	69	Renault	128	SHARAN	
PUNTO				AVANTIME		TIGUAN	
SCUDO.		Mitsubishi	70	CAPTUR		TOUAREG	
STRADA		ASX	70	CLIO		TOURAN	
TIPO		OUTLANDER			130	TRANSPORTER	
						INANOPUNIEK	177
ULYSSE	50	SPACE STAR	71	FLUENCE	133		

Alfa Romeo

➡ GIULIETTA

i	<u> </u>	/	£
Radio CD	Continental VP2 radio	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts	£ 228
	Continental VP2 navigation	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 322
Navigation	Magneti Marelli NAV GIULIETTA	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = radio code blocked or lost = Logo appears and then the unit restarts	£ 322 EXPRESS
	Harman VP4	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts	£ 322
	Continental / VDO / Siemens		
Display		error message = display damaged = display only shows the logo = screen opens with saccade or blocks when moving out or retracting = screen does not open and does not close	£ 228 EXPRESS



£ Bosch ALFA 955 CD unreadable = poor radio reception = one or more buttons £ 131 without function - System will not start - Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or **EXPRESS** impossible Radio CD Continental VP2 radio CD unreadable \blacksquare poor radio reception \blacksquare one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or £ 228 impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts **Continental VP2** navigation System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal £322 power consumption = Touchscreen does not work correctly = CD Inserting and ejecting of CD difficult or impossible \blacksquare radio code **Navigation** blocked or lost NAV MITO CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = £ 322 Inserting and ejecting of CD difficult or impossible incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly \blacksquare Logo appears and then the unit restarts

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £23



£ Blaupunkt Concert 2+ (EU AB2) Radio CD System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = £ 155 error message = abnormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible






incorrect temperature indication = incorrect mileage




i	 	/	£
	Grundig Concert (II)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible	£ 155
Radio CD	Blaupunkt Concert 2+ (EU AB2)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible	£ 155
CD changer	Panasonic Symphony (II)	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
Navigation	Blaupunkt RNS-D	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 357
	Audit Nevigation plus Roce Conv. Neur. Nev. New Cal. Return.	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 357
Cluster	1998 - 2006	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23











^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | SCRESS | Express option 72 hrs: + £ 23 |

PRICES VALID ONLY FOR PROFESSIONALS. Prices from 01/10/2020, subject to change. Non contractual pictures. All rights reserved.

BERLINGO

	ILINGO		
i	<u> </u>	<i>></i>	£
	Clarion RD1	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Clarion / VDO / Siemens RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Magneti Marelli SMEG + IV2 RADIO		
Multimedia System		System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work = cracked screen	£ 228 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
Navigation	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Magneti Marelli SMEG + IV2 NAV		
		System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work = cracked screen	£ 274 EXPRESS



BERLINGO

\mathbf{i}			£
Navigation	NEW Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
	Continental / VDO / Siemens		
Display		error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Jaeger BERLINGO I		
Cluster		no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

i	<u> </u>	/	£
Radio CD	Panasonic RD3 PANA	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Pioneer RDE	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Power steering control unit	Fujitsu DAE C1	permanent lost of power steering = unpredictable lost of power steering = engine warning light on	£ 138



:		,	£
1	Clarion / VDO / Siemens RD3		<u> </u>
Radio CD	Column / VDO / Siemens ADS	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RD4 / RD45		
	No.	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Blaupunkt 5 CD		
CD changer	• (F)	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit			
		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli RT3		
		System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Continental / VDO / Siemens		
Display [error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

Citroën C3

i	<u> </u>	<u> </u>	£
	Clarion / VDO / Siemens RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Continental / VDO / Siemens / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	NEW Clarion RD6	System will not start = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = USB playback does not work correctly = abnormal power consumption	£ 131 EXPRESS
CD changer	NEW Blaupunkt 5 CD	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Multimedia System	NEW Magneti Marelli SMEG+IV2 RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work = cracked screen	£ 228 EXPRESS
(4)	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349





			
i	<u> </u>	/	£
	NEW Magneti Marelli SMEG+IV2 NAV	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work = cracked screen	£ 274
	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Harman Becker RNEG Settle Prices Settle P	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Cluster	Continental C3 II	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165








C3 Aircross



C3 Picasso





i	<u> </u>	<i>></i>	£
Radio CD	Continental RD5	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = abnormal power consumption	£ 131 EXPRESS
CD changer	Blaupunkt 5 CD *** *** *** *** *** *** ***	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Multimedia System	Magneti Marelli SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
9 ,	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT4 = RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG NOO NAME OF STAFF PROOF SECURITY PRO	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS






\mathbf{i}	<u></u>		£
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
Navigation	Magneti Marelli SMEG+IV2 NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work = cracked screen	£ 274 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	error message = display damaged = no display = Display only shows the logo Continental / Sony error message = display damaged = no display = Display only	£ 228 EXPRESS	
Cluster	Johnson Controls 2004 - 2010	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
	Continental 2010 - 2018	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165


► C4 AIRCROSS

i	 	<u> </u>	£
Radio CD	Mitsubishi RADIO 1CD	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = sound problem = error message = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 228 EXPRESS
	NEW Mitsubishi DY-5MW3R69	Contact us	£ 228
CD changer	Mitsubishi RADIO 6CD	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = sound problem = error message = abnormal power consumption = Inserting and ejecting of CD difficult or impossible	£ 228 EXPRESS
Navigation	Mitsubishi MMCS	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Inserting and ejecting of CD difficult or impossible	£ 458
	Mitsubishi NR242	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Inserting and ejecting of CD difficult or impossible	£ 458

C4 CACTUS



C4 PICASSO



^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23

→ C4 Picasso

	100330		
i	<u> </u>		£
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3		
		System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
Navigation	Magneti Marelli SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Continental / Sony Fixing My Brain Fixing My Brain Pere Ob/12 Pere Ob/12	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS



i	<u> </u>	/	£
Radio CD	Clarion / VDO / Siemens RD2 / RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Multimedia System	Magneti Marelli SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Clarion RT2	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS



^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23





i	<u> </u>	/	£
	Harman Becker NG4	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = battery discharge	£ 322 EXPRESS
Navigation	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
	Magneti Marelli SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
Display	Continental / Sony Nother in American and A stronger	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Charter	Jaeger	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Cluster	C5 II	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165



i		/	£
Radio CD	Blaupunkt / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Cluster	Borg / Jaeger	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165




i	 		£
Radio CD	Clarion / VDO / Siemens RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 Express
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS








C-CROSSER



← C-ELYSEE







— JUMPER

i	<u> </u>		£
Radio CD	Blaupunkt / Bosch RD4 250CD	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Delphi F250FL	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 131 EXPRESS
	Continental VP1	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131
	Continental VP2 RADIO	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts	£ 228
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Continental VP2 NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 322



^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | Express option 72 hrs: + £ 23

→ JUMPER



JUMPY







£ Magneti Marelli RT3 System will not start = Display only shows the logo = Radio £ 322 switches on by itself = one or more buttons without function = CD unreadable - Mapping is not shown correctly Magneti Marelli RT4 / RT5 System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = £ 322 CD unreadable = No Bluetooth fonction = Mapping is not shown System will not start = Radio switches on by itself = one or **Navigation Harman Becker RNEG** more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor £ 322 radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge abnormal power consumption = CD is ejected without reason or source changes by itself Magneti Marelli RT6 / RNEG2 System will not start \blacksquare Logo appears and then the unit restarts \blacksquare Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction £ 322 aesthetic repair = Mapping is not shown correctly = Insert **EXPRESS** navigation CD or check in progress on display = Display frozen sound problem internal noise noise through the speakers Satellite reception problem **Continental NAC** system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception £ 322 problem = sound problem = error message Continental / VDO / Siemens £ 228 error message = display damaged = no display = Display only shows the logo EXPRESS Steering wheel remote control airbag light is on, problems on the signal control module, on the £ 165 wiping control module, on the horn control unit

NEMO





i	<u> </u>	/	£
Radio CD	Clarion / VDO / Siemens RD2 / RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit	NEW	Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Clarion RT2	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322
	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | SYPRESS Express option 72 hrs: + £ 23

XSARA PICASSO

i	<u> </u>	/	£
Radio CD	Clarion / VDO / Siemens RD2 / RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

DOKKER



DUSTER



LODGY







SANDERO






	J		
i		/	£
Radio CD	Blaupunkt / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
Multimedia System	Magneti Marelli SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
Body control unit	NEW	Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
Navigation	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Magneti Marelli SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 322 EXPRESS
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Continental / Sony	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS

















^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23

→ DS5













⇒ 500



➡ 500L - 500X



➡ DOBLO



DUCATO

£ Blaupunkt / Bosch RD4 250CD CD unreadable = poor radio reception = one or more buttons £ 131 without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or **EXPRESS** impossible = anormal power consumption 2 3 Delphi F250FL CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by £131 itself = sound problem = remote control does not work correctly = **EXPRESS** Inserting and ejecting of CD difficult or impossible = radio code **Continental VP1** Radio CD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 131 itself = sound problem = inserting and ejecting of CD difficult or **Continental VP2 RADIO** CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or £ 228 impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts Magneti Marelli RT3 System will not start = Display only shows the logo = Radio £ 322 switches on by itself = one or more buttons without function = CD 0 **EXPRESS** unreadable Mapping is not shown correctly **Navigation Continental VP2 NAVIGATION** System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 322 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost
























PANDA



PUNTO



SCUDO




STRADA







ULYSSE



→ C-MAX

i	<u> </u>		£
Radio CD	Visteon 6000CD	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = one or more buttons without function = AUX input is not working correctly = abnormal power consumption	£ 147
	Visteon RADIO AHU	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = abnormal power consumption	£ 147
	Sony	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 147
Navigation	Bosch HSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
	Bosch LSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
Display	NEW FoMoCo DISPLAY NAV AHU	no display or faded display	£ 228 EXPRESS
Cluster	Visteon 2007 →	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 155

➡ FIESTA

i	<u> </u>	<u> </u>	£
Radio CD	Visteon 6000CD	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = one or more buttons without function = AUX input is not working correctly = abnormal power consumption	£147
	Visteon RADIO AHU	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = abnormal power consumption	£147
Display	NEW FoMoCo DISPLAY NAV AHU	no display or faded display	£ 228 EXPRESS
Cluster	Visteon 2007 →	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 155

FOCUS

		<u> </u>	£
Radio CD	Visteon 6000CD	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = one or more buttons without function = AUX input is not working correctly = abnormal power consumption	£ 147
	Sony C307 / C214	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 147
	Visteon RADIO AHU	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = abnormal power consumption	£ 147
Navigation	Bosch HSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
	Bosch LSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
Display	NEW FoMoCo DISPLAY NAV AHU	no display or faded display	£ 228 EXPRESS
Cluster	Visteon 2007 →	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 155

FUSION











MONDEO




RANGER



S-MAX

i	<u> </u>	/	£
Radio CD	Sony Sony	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£147
	Visteon 6000CD	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = one or more buttons without function = AUX input is not working correctly = abnormal power consumption	£147
Navigation	Bosch HSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
	Bosch LSRNS	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem	£ 357
Cluster	Visteon 2007 →	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 155

TRANSIT






← CIVIC


i	<u> </u>		£
Navigation	Clarion QY5005	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 322
	Clarion QY5008	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 322
	Clarion QY5017 / QY5026	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 322





^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23


← CR-Z








➡ INSIGHT







^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23


















➡ IX35



SANTA FE



🚗 TUCSON II



^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23





RENEGADE

i E

Continental VP2 RADIO







CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts

£ 228

Continental VP2 NAVIGATION



System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = inserting and ejecting of CD difficult or impossible = radio code blocked or lost

£ 322

Navigation



Harman VP4



CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen = radio code blocked or lost = Touchscreen does not work correctly = Logo appears and then the unit restarts

£ 322

→ CEE'D







SORENTO



SPORTAGE



VENGA




^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23

MUSA



PHEDRA




















OUTLANDER



SPACE STAR




^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23

→ 350 Z













ALMERA


















⇔ GTR

i	<u> </u>		£
	Clarion CONNECT PREMIUM (X9)	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 450
Navigation	Clarion CONNECT PREMIUM (X9)	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 450
	Clarion EV NAVI	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible = No Bluetooth fonction	£ 450







£ Blaupunkt / Bosch NISSAN CONNECT System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound £ 322 problem = Mapping is not shown correctly = Satellite reception **EXPRESS** problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen **Bosch NISSAN CONNECT 2 Navigation** System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound £ 322 problem Mapping is not shown correctly Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen **Bosch NISSAN CONNECT 3** System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound £ 322 problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen






MICRA



MURANO



NAVARA

	VAINA		
i			£
	Clarion 1CD	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 155
Radio CD	Clarion 1CD Clari	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 155
	Daewoo	no display or faded display = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 155 EXPRESS
CD changer	Clarion 6CD NISSAN 1 2 3 2 3 6	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
((() () x €10	Clarion 6CD WO COMMENT WO THE STATE OF THE	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
Navigation	Clarion CONNECT PREMIUM (X9)	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 450
	Bosch NISSAN CONNECT 3	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen	£ 322
Display	Clarion	error message = display damaged = no display = Display only shows the logo	£ 228

NOTE

£ Blaupunkt MMCD / MMRCD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 155 itself = sound problem = abnormal power consumption = Inserting and ejecting of CD difficult or impossible Clarion 1CD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by Radio CD £ 155 itself = sound problem = inserting and ejecting of CD difficult or impossible Daewoo no display or faded display = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult £ 155 **EXPRESS** or impossible = radio code blocked or lost **Clarion** 6CD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 187 itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen CD changer Blaupunkt / Bosch MMR IDC CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 187 itself = sound problem = abnormal power consumption = Inserting and ejecting of CD difficult or impossible Blaupunkt / Bosch NISSAN CONNECT







System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly a aesthetic repair incorrect display on screen

£ 322

EXPRESS

Bosch NISSAN CONNECT 2



System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen

£ 322

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23

PATHFINDER



PATROL



PRIMERA







QASHQAI

	SHUAI		
i	<u></u>		£
Radio CD	Clarion 1CD	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 155
	Daewoo TMAAM CD TM MIX CD TA MY MIX MY MY MY MIX MY M	no display or faded display = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 155 Express
	Clarion 6CD NOCE PHONE ROUTE ROUTE APT MASS TA PTT MASS T 2 3 4 5 6	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
CD changer	Blaupunkt / Bosch MMR IDC	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = abnormal power consumption = Inserting and ejecting of CD difficult or impossible	£ 187
	Clarion 6CD	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
Navigation	Blaupunkt / Bosch NISSAN CONNECT	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen	£ 322 EXPRESS
	Bosch NISSAN CONNECT 3	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen	£ 322
Display	Clarion	error message = display damaged = no display = Display only shows the logo	£ 228

A X-TRAIL

	· // // —		
i	<u></u>		£
Dadia CD	Clarion 1CD	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 155
Radio CD	Clarion 1CD The state of the s	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 155
CD changer	Clarion 6CD CO CONTROL OF THE PROPERTY OF THE	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
₩ X CD	Clarion 6CD Clarion 6CD Clarion 6CD Clarion 6CD	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible = incorrect display on screen	£ 187
	Bosch NISSAN CONNECT	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen	£ 322 EXPRESS
Navigation	Bosch NISSAN CONNECT 3	System will not start = Radio switches on by itself = radio code blocked or lost = poor radio reception = CD unreadable = sound problem = Mapping is not shown correctly = Satellite reception problem = incorrect display on screen = Touchscreen does not work correctly = aesthetic repair = incorrect display on screen	£ 322
	Clarion CONNECT PREMIUM (X9) OUT DEST NAPO SETTING STATUS DEACK VOICE 1 2 3 4 5 4	system will not start = radio switches on by itself = one or more buttons without function = poor radio reception = mapping is not shown correctly = sound problem = satellite reception problem = error message = CD unreadable = inserting and ejecting of CD difficult or impossible = no Bluetooth fonction	£ 450
Display	Clarion	error message = display damaged = no display = Display only shows the logo	£ 228









Opel / Vauxhall ASTRA

i	<u> </u>	1	£
Radio CD	Blaupunk CD30	Contact us	£138
Multimedia System	LG RADIO R 4.0 INTELLILINK	Contact us	£ 274
	LG BYOM1	Contact us	£ 274
	Bosch NAVI 900	Contact us	£ 274
Navigation	Delphi NAVI 900 INTELLILINK	Contact us	£ 274
	Panasonic NAVI 950	Contact us	£ 274
	Bosch DVD 800	Contact us	£ 274

→ ASTRA


i	<u> </u>		£
Navigation	Bosch NAVI 600	Contact us	£ 274
	Bosch CD 500	Contact us	£ 274
Display	Delphi DISPLAY NAVI900	Contact us	£ 228

CASCADA

i	<u> </u>		£
	Bosch NAVI 900	Contact us	£ 274
Navigation	Panasonic NAVI 950	Contact us	£ 274
	Bosch NAVI 600	Contact us	£ 274

Opel / Vauxhall

CORSA



INSIGNIA

Bosch NAVI 900 Contact us Delphi NAVI 900 INTELLILINK Navigation		TOI VII V		
Contact us Delphi NAVI 900 INTELLILINK Navigation Contact us E 274		<u>***</u>		£
Navigation Contact us		Bosch NAVI 900	Contact us	£ 274
Bosch DVD 800	Navigation	***************************************	Contact us	£ 274
Contact us £ 274		Bosch DVD 800	Contact us	£ 274



→ INSIGNIA

i	<u> </u>	<u> </u>	£
Navigation	Bosch NAVI 600	Contact us	£ 274
	Bosch CD 500	Contact us	£ 274

MERIVA

i	<u></u>	1	£
	Bosch NAVI 900	Contact us	£ 274
	Bosch NAVI 950	Contact us	£ 274
Navigation	Bosch DVD 800	Contact us	£ 274
	Bosch NAVI 600	Contact us	£ 274
	Bosch CD 500	Contact us	£ 274

Opel / Vauxhall

MOKKA



ZAFIRA

i	<u> </u>	1	£
Multimedia System	LG RADIO R 4.0 INTELLILINK	Contact us	£ 274
. (F)	LG BYOM1	Contact us	£ 274
	Bosch TOUCH N CONNECT	Contact us	£ 274
Navigation	Bosch NAVI 900	Contact us	£ 274
	Bosch NAVI 950	Contact us	£ 274
	Bosch NAVI 600	Contact us	£ 274
Display	NEW DISPLAY NAVI950	Contact us	£ 228

→ 106

i	<u> </u>		£
Radio CD	Clarion RD1	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349

→ 107



→ 1007

•			C
1	<u> </u>		£
Radio CD	Clarion / VDO / Siemens RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Clarion / VDO / Siemens		
Display		error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

Peugeot 206

i		<i>></i>	£
Radio CD	RD1	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Clarion RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Display	Clarion / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS







⇒ 207







i	<u> </u>	/	£
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Cluster	VDO	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Sunroof control unit	CTE 207	impossible opening = closing of the roof	£ 138
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

Peugeot 208

i	<u> </u>		£
Radio CD	Pioneer RDE	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Multimedia System	Magneti Marelli SMEG / SMEG+ RADIO	system will not start = logo appears and then the unit restarts = radio switches on by itself = poor radio reception = no Bluetooth fonction = sound problem = internal noise = display frozen = external CD playback does not work	£ 228 EXPRESS
9 ,	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli SMEG / SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / Sony	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control	COM2008	airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

⇒ 2008

i	<u> </u>		£
Radio CD	Pioneer RDE	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Multimedia System	Magneti Marelli SMEG / SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
. 	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit	NEW THE PROPERTY OF THE PROPER	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli SMEG / SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / Sony WAS THE PROPERTY OF THE PR	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control	COM2008	airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

Peugeot







i	<u></u>	/	£
Radio CD	Clarion / VDO / Continental RD3 / RD4	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
CD changer	Blaupunkt 5 CD	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
	Magneti Marelli RT4	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165



i	<u> </u>	<u> </u>	£
Radio CD	Continental / VDO / Siemens / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
Radio CD	NEW Clarion RD6	System will not start = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = USB playback does not work correctly = abnormal power consumption	£ 131 EXPRESS
CD changer	Blaupunkt 5 CD ***********************************	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Multimedia System	Magneti Marelli SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
1 0	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349





i			£
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
Navigation	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Harman Becker NG4	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = battery discharge	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Magneti Marelli SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Continental / Sony 1910 22 AMDER 22 16-15 PRAITY AND	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS



308









3008

i			£
Navigation	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Harman Becker NG4	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = battery discharge	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = display only shows the logo = screen opens with saccade or blocks when moving out or retracting = screen does not open and does not close	£ 228 EXPRESS
	Johnson Controls VTH / HUD	mechanical noise = no mechanical function = Display does not come on = blocked screen	£ 228 EXPRESS
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165



i			£
Radio CD	Clarion RM2	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131
	Clarion RD2 / RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	VDO / Siemens NAV VDO	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible	£ 322
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165



i		*	£
Radio CD	Continental RD4	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3 / RT4	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS




^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23 |

PRICES VALID ONLY FOR PROFESSIONALS. Prices from 01/10/2020, subject to change. Non contractual pictures. All rights reserved.









→ 4008



^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | SAPRESS Express option 72 hrs: + £ 23

Peugeot 508


i	<u> </u>		£
Radio CD	Continental RD5	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = abnormal power consumption	£ 131 EXPRESS
Multimedia System	Magneti Marelli SMEG+ RADIO	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = External CD playback does not work	£ 228 EXPRESS
.	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit	Charles Charle	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
Navigation	Magneti Marelli SMEG+ NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work	£ 274 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322





i	<u></u>	<i>></i>	£
	Continental / Sony	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Display O	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
	Johnson Controls VTH / HUD	mechanical noise = no mechanical function = Display does not come on = blocked screen	£ 228 EXPRESS
Cluster	1	defective needles. For other faults: please contact us	£ 165
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

⇒ 5008









Peugeot 607

i	<u> </u>	/	£
Radio CD	Clarion RM2	CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131
	Continental RD4	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Clarion RT2	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS







Peugeot 807

•			C
1	<u> </u>		t
	Clarion / VDO RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Continental / VDO / Siemens / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Johnson Controls AVS DIN BOX B58	CD unreadable = System will not start = sound problem = Inserting and ejecting of CD difficult or impossible	£ 228
CD changer	Clarion CDC	CD unreadable = sound problem = Inserting and ejecting of CD difficult or impossible	£ 165 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS





BIPPER









→ BOY	CR		
i	<u> </u>	<u> </u>	£
Body control unit	NEW	Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit	The state of the s	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT3	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = Mapping is not shown correctly	£ 322 EXPRESS
Navigation	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Continental VP2 NAVIGATION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible = radio code blocked or lost	£ 322
Display	Magna X250	error message = display damaged = display only shows the logo = screen opens with saccade or blocks when moving out or retracting = screen does not open and does not close	£ 228
	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Cluster	06 ■ 2014 →	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165

EXPERT

i _	<u></u>		£
	Clarion RD3	CD unreadable = poor radio reception = one or more buttons without function = system will not start = Radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Continental / VD0 / Siemens / Bosch RD4 / RD45	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Clarion RD6	System will not start = Radio switches on by itself = poor radio reception = No Bluetooth fonction = sound problem = internal noise = Display frozen = USB playback does not work correctly = abnormal power consumption	£ 131 EXPRESS
Multimedia System	Bosch RCC	Contact us	Contact us
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit		Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349






i			£
Navigation	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Continental NAC	system will not start = radio switches on by itself = no Bluetooth fonction = mapping is not shown correctly = poor radio reception = logo appears and then the unit restarts = Satellite reception problem = sound problem = error message	£ 322
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23

⇒ ION



PARTNER





⇔ PARTNER

i	<u></u>		£
Engine control unit	Hamilton	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
	Magneti Marelli RT4 / RT5	System will not start = Display only shows the logo = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly	£ 322
Navigation	Harman Becker RNEG Mod Public Strip Strip Public Strip Strip	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322 EXPRESS
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
	Magneti Marelli SMEG+IV2 NAV	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = poor radio reception = No Bluetooth fonction = Mapping is not shown correctly = sound problem = internal noise = Satellite reception problem = Display frozen = External CD playback does not work = cracked screen	£ 274 EXPRESS
Display	Continental / VDO / Siemens	error message = display damaged = no display = Display only shows the logo	£ 228 EXPRESS
Cluster	Jaeger PARTNER I	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Steering wheel remote control		airbag light is on, problems on the signal control module, on the wiping control module, on the horn control unit	£ 165



;		<u> </u>	£
Radio CD	Continental RD4	CD unreadable = poor radio reception = one or more buttons without function = system will not start = radio switches on by itself = sound problem = inserting and ejecting of CD difficult or impossible = anormal power consumption	£ 131 EXPRESS
	Continental / VDO / Siemens / Bosch RD45	No Bluetooth fonction = CD unreadable = Inserting and ejecting of CD difficult or impossible = System will not start = sound problem = poor radio reception = USB playback does not work correctly = one or more buttons without function = AUX input is not working correctly = abnormal power consumption	£ 131 EXPRESS
Body control unit		Anti-Start-Code-Problem = Wiper problem = Centralization problem = Air conditioning problem	£ 210
Engine control unit	The state of the s	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	Harman Becker NG4	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = battery discharge	£ 322 EXPRESS
	Harman Becker RNEG	System will not start = Radio switches on by itself = one or more buttons without function = CD unreadable = No Bluetooth fonction = sound problem = Satellite reception problem = poor radio reception = dial knob without function = aesthetic repair = Display only shows the logo = Mapping is not shown correctly = error message = noise through the speakers = battery discharge = abnormal power consumption = CD is ejected without reason or source changes by itself	£ 322
	Magneti Marelli RT6 / RNEG2	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = aesthetic repair = Mapping is not shown correctly = Insert navigation CD or check in progress on display = Display frozen = sound problem = internal noise = noise through the speakers = Satellite reception problem	£ 322 EXPRESS
Display	Continental / VDO / Siemens / Bosch	error message = display damaged = display only shows the logo = screen opens with saccade or blocks when moving out or retracting = screen does not open and does not close	£ 228 EXPRESS

Peugeot

RIFTER



Renault

AVANTIME



CAPTUR

HUMAX Automotive / Daewoo RADIO CLASSIC Radio CD System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible £ 131 **Continental RADIO R-LINK1** System will not start = Radio switches on by itself = one or more Multimedia System buttons without function \blacksquare poor radio reception \blacksquare CD unreadable £ 131 ■ No Bluetooth fonction ■ sound problem ■ abnormal power consumption \blacksquare Remote control does not work correctly \blacksquare Inserting and ejecting of CD difficult or impossible Engine control unit Vehicle does not start = Calculator locked = EGR valve is not £ 257 / working properly = Impossible to learn the EGR valve = motor £ 349 stops = Vehicle has no engine power **LG** MEDIANAV / MEDIANAV EVOLUTION System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function £ 228 poor radio reception = Mapping is not shown correctly = sound EXPRESS problem = Satellite reception problem = error message = abnormal power consumption - Touchscreen does not work correctly Navigation **TomTom** R-LINK1 error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by £ 228 itself = mapping is not shown correctly Body control unit £210 Contact us

→ CLIO





LG MEDIANAV / MEDIANAV EVOLUTION System will not start \blacksquare Logo appears and then the unit restarts \blacksquare Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal £ 228 **EXPRESS** power consumption = Touchscreen does not work correctly Navigation TomTom R-LINK1 error message = system will not start = Touchscreen does not £ 228 work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly Johnson Controls CLIO II no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = £138 incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage Visteon CLIO III Cluster no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = £138 incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage Visteon CLIO IV no fonction at all \blacksquare no lighting \blacksquare one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication £ 138 incorrect temperature indication = incorrect mileage = incorrect clock and radio information Body control unit £210 Contact us

ESPACE

	ACE		
i	***		£
Radio CD	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Clarion ABB TUNER	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = No Bluetooth fonction = sound problem = anormal power consumption	£ 165 EXPRESS
CD changer	Alpine 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165
(((() x 60	Clarion 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165 EXPRESS
Navigation	VDO CNI 1	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	Harman Becker CGI	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	Jaeger Valeo ESPACE III B2I	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 165
Cluster	Sagem / Johnson Controls ESPACE IV	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 138
	ESPACE IV	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 138
Body control unit		Contact us	£ 210

→ FLUENCE

i	<u> </u>	<i>></i>	£
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Blaupunkt RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
Navigation	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Body control unit		Contact us	£ 210

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23

KANGOO

i	<u> </u>	<i> </i>	£
	Blaupunkt RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	VDO UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Blaupunkt RADIOSAT CLASSIC2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	HUMAX Automotive / Daewoo RADIO CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
Engine control unit	SIEMENS INTERNATIONAL INTERNAT	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349





i	<u> </u>	<u> </u>	£
Navigation	Harman Becker CGI	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Cluster	Jaeger KANGOO I PHASE 1 (1997-2003)	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£138
Body control unit	C.C. Distriction of the Control of t	Contact us	£ 210

KOLEOS

i	<u> </u>	<u> </u>	£
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
	Clarion ABB TUNER	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = No Bluetooth fonction = sound problem = anormal power consumption	£ 165 EXPRESS
CD changer	Clarion 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165 EXPRESS
Navigation	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Body control unit		Contact us	£ 210

LAGUNA

i	<u></u>	<i> </i>	£
	VDO UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	VDO TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
	Clarion ABB TUNER	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = No Bluetooth fonction = sound problem = anormal power consumption	£ 165 EXPRESS
CD changer	Alpine 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165
	Clarion 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165 EXPRESS
Engine control unit	SIEMENS	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349



→ LAGUNA

i	***		£
	VDO CNI 1	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	Xanavi NAVI CD Report O Bladoott O	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
Navigation	Harman Becker CGI	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	VDO CNI2	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Airco Panel	Delphi LAGUNA II	incorrect display ■ one or more buttons without function	£ 147 EXPRESS
Cluster	Jaeger LAGUNA II BG	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 138
	LAGUNA III	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£138
Body control unit		Contact us	£ 210

LATITUDE







► MASTER

i	 	<i></i>	£
	HUMAX Automotive / Daewoo RADIO CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
Radio CD	VDO TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Navigation	VDO CNI 1	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	NEW LG MEDIANAV / MEDIANAV EVOLUTION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly	£ 228 EXPRESS
Body control unit		Contact us	£ 210

MEGANE

i	<u> </u>	<i>></i>	£
	Philips TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	VDO TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Philips TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Blaupunkt / Bosch RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
Engine control unit	SIEMENS	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349



→ MEGANE

i	<u> </u>	<u> </u>	£
Navigation	VDO CNI 1	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	VDO CNI 2	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	Harman Becker CGI	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Cluster	MEGANE 2	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage = incorrect clock and radio information	£ 138
	VDO MEGANE 3	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage	£ 138
Body control unit		Contact us	£ 210

MODUS



SAFRANE



- SCENIC

i	<u> </u>	<i>/</i>	£
	VDO TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Radio CD	Blaupunkt RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£131 EXPRESS
	Clarion ABB TUNER	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = No Bluetooth fonction = sound problem = anormal power consumption	£165 EXPRESS
CD changer	Clarion 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165 EXPRESS
	Clarion 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165 EXPRESS
	Alpine 6CD	system will not start = CD unreadable = inserting and ejecting of CD difficult or impossible = radio switches on by itself = one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 165





i		/	£
Engine control unit	SIEMENS	Vehicle does not start = Calculator locked = EGR valve is not working properly = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349
Navigation	VDO CNI 1	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	VDO CNI 2	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	Harman Becker CGI	System will not start = CD unreadable = Inserting and ejecting of CD difficult or impossible = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = AUX input is not working correctly = incorrect display on screen	£ 413
	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
Cluster	Johnson Controls SCENIC II	no fonction at all = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage = device works aleatoric = incorrect driving information = incorrect clock and radio information	£ 138
	SCENIC III	no fonction at all = no lighting = one or more LED do not work correctly = incorrect display on screen = incorrect speed display = incorrect tachometer indication = incorrect fuel gauge indication = incorrect temperature indication = incorrect mileage = incorrect clock and radio information	£ 138
Body control unit		Contact us	£ 210

→ TRAFIC

i	<u> </u>	<i> </i>	£
Radio CD	VDO UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
	Blaupunkt RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS
Multimedia System	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = abnormal power consumption = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible	£ 131
Navigation	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228
	LG MEDIANAV / MEDIANAV EVOLUTION	System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function = poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly	£ 228 EXPRESS
Body control unit		Contact us	£ 210

TWINGO

- 1 V V						
i	<u> </u>	/	£			
Radio CD	VDO TUNER LIST / UPDATE LIST	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS			
	Blaupunkt RADIOSAT CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS			
	Blaupunkt / Bosch RADIOSAT R2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131			
	Blaupunkt RADIOSAT CLASSIC2	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS			
	Continental RADIOSAT R3 (R-PLUG&RADIO+)	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131 EXPRESS			
	HUMAX Automotive / Daewoo RADIO CLASSIC	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = anormal power consumption = inserting and ejecting of CD difficult or impossible	£ 131			
Multimedia System	Continental RADIO R-LINK1	System will not start = Radio switches on by itself = one or more buttons without function = poor radio reception = CD unreadable = No Bluetooth fonction = sound problem = abnormal power consumption = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible	£ 131			
Engine control unit	SIEMENS	Vehicle does not start = Calculator locked = EGR valve is not working property = Impossible to learn the EGR valve = motor stops = Vehicle has no engine power	£ 257 / £ 349			
Navigation	TomTom R-LINK1	error message = system will not start = Touchscreen does not work correctly = Satellite reception problem = radio switches on by itself = mapping is not shown correctly	£ 228			



TWINGO



VELSATIS











ALHAMBRA





















→ IBIZA














TOLEDO



FABIA







OCTAVIA

Technisat / Visteon DANCE Radio CD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 155 itself = sound problem = inserting and ejecting of CD difficult or Blaupunkt / Delphi BOLERO system will not start = logo appears and then the unit restarts CD changer radio switches on by itself one or more buttons without function = poor radio reception = sound problem = error message = abnormal power consumption = touchscreen does not work £ 187 correctly = CD unreadable = inserting and ejecting of CD difficult or impossible Blaupunkt / Bosch AMUNDSEN System will not start = Logo appears and then the unit restarts = radio switches on by itself = one or more buttons without function poor radio reception mapping is not shown correctly sound £ 357 problem \blacksquare satellite reception problem \blacksquare error message \blacksquare anormal power consumption \blacksquare CD unreadable \blacksquare inserting and ejecting of CD difficult or impossible **Continental COLUMBUS** System will not start \blacksquare Logo appears and then the unit restarts \blacksquare radio switches on by itself - one or more buttons without function poor radio reception mapping is not shown correctly sound £ 357 problem = satellite reception problem = error message = anormal Navigation power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible **Panasonic AMUNDSEN 2** System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible Harman COLUMBUS 2 System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible

RAPID



ROOMSTER

Technisat / Visteon DANCE CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 155 itself = sound problem = inserting and ejecting of CD difficult or Radio CD Blaupunkt / Bosch / Delphi SWING CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 155 itself \blacksquare sound problem \blacksquare inserting and ejecting of CD difficult or impossible Blaupunkt / Bosch AMUNDSEN System will not start \blacksquare Logo appears and then the unit restarts \blacksquare radio switches on by itself = one or more buttons without function poor radio reception = mapping is not shown correctly = sound £ 357 problem = satellite reception problem = error message = anormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible **Navigation Continental COLUMBUS** System will not start = Logo appears and then the unit restarts = radio switches on by itself = one or more buttons without function ■ poor radio reception ■ mapping is not shown correctly ■ sound £ 357 problem = satellite reception problem = error message = anormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible

SUPERB








^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS | Express option 72 hrs: + £ 23





FORESTER



→ IMPREZA








LEVORG







G.VITARA



JIMNY










Volkswagen

AMAROK




CADDY







power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible



Volkswagen

GOLF







£ Blaupunkt / Bosch RNS310 System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable - Inserting and ejecting of CD difficult or impossible Continental / VDO / Siemens RNS510 (MFD3) System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal Navigation power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible **Delphi / Panasonic / Technisat DISCOVER MEDIA** System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible Harman DISCOVER PRO System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | Express option 72 hrs: + £ 23

Volkswagen

→ JETTA



NEW BEETLE / COCCINELLE







Blaupunkt / Delphi RCD510







CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen

£ 187

Technisat RNS315



System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible

£ 357

Navigation



Continental / VDO / Siemens RNS510 (MFD3)



System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable \blacksquare Inserting and ejecting of CD difficult or impossible

£357

Delphi / Panasonic / Technisat DISCOVER MEDIA




System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible

£ 357

PASSAT

£ Blaupunkt / Grundig / Visteon RCD300 Radio CD CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 155 itself = sound problem = inserting and ejecting of CD difficult or Blaupunkt / Bosch / Panasonic RCD500 CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 187 itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen CD changer Blaupunkt / Delphi RCD510 CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 187 itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen **Blaupunkt RNS2** System will not start = Logo appears and then the unit restarts = radio switches on by itself = one or more buttons without function poor radio reception mapping is not shown correctly sound £ 357 problem \blacksquare satellite reception problem \blacksquare error message \blacksquare anormal power consumption = CD unreadable = inserting and ejecting of CD difficult or impossible Blaupunkt / Bosch RNS310 System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function ■ poor radio reception ■ Mapping is not shown correctly ■ sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible **Navigation Technisat RNS315** System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception = Mapping is not shown correctly = sound problem = Satellite reception problem = error message = abnormal £ 357 power consumption = Touchscreen does not work correctly = CD unreadable = Inserting and ejecting of CD difficult or impossible Continental / VDO / Siemens RNS510 (MFD3) System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable - Inserting and ejecting of CD difficult or impossible





POLO




SCIROCCO

£ Blaupunkt / Bosch / Delphi RCD310 Radio CD CD unreadable = poor radio reception = one or more buttons without function System will not start Radio switches on by £ 155 itself = sound problem = inserting and ejecting of CD difficult or impossible Blaupunkt / Bosch / Panasonic RCD500 CD unreadable ■ poor radio reception ■ one or more buttons without function - System will not start - Radio switches on by £ 187 itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen CD changer Blaupunkt / Delphi RCD510 CD unreadable = poor radio reception = one or more buttons without function = System will not start = Radio switches on by £ 187 itself = sound problem = Remote control does not work correctly = Inserting and ejecting of CD difficult or impossible incorrect display on screen Continental / VDO / Siemens RNS510 (MFD3) System will not start = Logo appears and then the unit restarts = Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD **Navigation** unreadable Inserting and ejecting of CD difficult or impossible Delphi / Panasonic / Technisat **DISCOVER MEDIA** System will not start - Logo appears and then the unit restarts -Radio switches on by itself = one or more buttons without function poor radio reception = Mapping is not shown correctly = sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible

^{*} Prices excluding VAT, including: transport, repair and controls, 1 year warranty, hotline | EXPRESS Express option 72 hrs: + £ 23

SHARAN



TIGUAN





TIGUAN



TOUAREG



TOURAN



TOURAN

£ Delphi / Panasonic / Technisat System will not start - Logo appears and then the unit restarts -**DISCOVER MEDIA** Radio switches on by itself = one or more buttons without function poor radio reception Mapping is not shown correctly sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD **Navigation** unreadable = Inserting and ejecting of CD difficult or impossible Harman DISCOVER PRO System will not start - Logo appears and then the unit restarts -Radio switches on by itself \blacksquare one or more buttons without function poor radio reception = Mapping is not shown correctly = sound £ 357 problem = Satellite reception problem = error message = abnormal power consumption = Touchscreen does not work correctly = CD unreadable Inserting and ejecting of CD difficult or impossible


TRANSPORTER





How to create your account on reparlab.com within few clics





faurecia clarion

ELECTRONICS

CLARION EUROPE S.A.S. 244, rue du Pré à Varois 54670 CUSTINES - France



Tel. 0033 383 494 420 service24.cef@faurecia.com

www.reparlab.com